


## ONTARIO COUNTY BEACH PARK

Ontario County Beach Park is a 0.6 acre park with approximately 450 feet of shoreline. The park is located on State Route 364 - East Lake Road, 4 miles south of the City of Canandaigua.

The park features four picnic sites with grills and seating, a lawn area, a restroom, and parking for 18 vehicles. A large stone retaining wall was constructed in the earlier part of the 20th century to protect East Lake Road from wave and ice action. There is an approximately 7 foot vertical drop to lake level from the wall. Swimming is prohibited at this site.

Ontario County Sewer District Pump Station 6-E is located on the north end of the property.

### PROJECT SITE CONDITIONS



### SITE DATA

EXISTING FEATURE	ONTARIO COUNTY BEACH PARK
<b>Parking and Green Infrastructure</b>	1. Standard asphalt paving with limited handicap accessibility
	2. 18 parking spaces
	3. Boulder buffer
	4. Parking island/buffer
	5. 8 existing trees
<b>Existing Pathway</b>	6. Path to restroom, no picnic table or waterfront access
<b>Shelter</b>	7. Restroom facility
<b>Additional Features</b>	8. Pump station
	9. Chain link fencing
	10. 6 picnic tables
	11. 3 layered stone retaining wall

## DEEP RUN PARK

Deep Run Park is a 1 acre park with approximately 353 feet of shoreline located one mile south of Ontario County Beach Park.

The park features a swimming beach, lawn area, picnic sites with grills and seating, a restroom/ changing area and parking for 36 vehicles.

Deep Run is a tributary that enters Canandaigua Lake at the northern border of the park. Accumulated out-wash and debris are periodically dredged pursuant to a permit from the NYSDEC. Portions of the designated swimming have become too shallow due to sedimentation and are closed to swimming.

### PROJECT SITE CONDITIONS



### SITE DATA

EXISTING FEATURE	DEEP RUN BEACH PARK
<b>Parking and Green Infrastructure</b>	1. Standard asphalt paving with blue highlighted handicap spaces
	2. 36 parking spaces
	3. Turning area at north
	4. Gravel island/buffer
	5. 6 existing trees (north 4 died at end of season last year)
<b>Existing Pathway</b>	6. No accessible pathway to restroom or picnic tables
<b>Shelter</b>	7. Restroom and storage facility
<b>Additional Features</b>	8. 3 layered stone retaining wall
	9. 1 lifeguard chair
	10. 9 picnic tables
	11. Guardrail